## AUBURN WATER SYSTEM, INC

3097 LOCKE LN CRESTVIEW, FL 32536 850-682-1258 OR 850-682-3413 ~ FAX 850-683-1151



## **Trouble Spot Check List**

- WATER TANK ON COMMODE:
  A) SEEPING LEAD VALVE CAUSING OVERFLOW
  - B) BALL OR FLAP VALVE NOT SEATING.
- 2. WATER HEATER FILLING OR LEAKING
- 3. DRIPPING FAUCETS IN TUB, SHOWER, LAVATORY, SINK, OUTSIDE FAUCETS LEAKING, ETC.
- 4. RELIEF VALVE ON WATER HEATER OPEN OR SEEPING.
- 5. OUTSIDE FAUCET OPEN OR DRIPPING.
- 6. WASHER OR DISHWASHER FEED VALVE OPEN OR SEEPING.
- 7. HOSE IN YARD TURNED ON OR LEAKING.
- 8. UNKNOWN LINES IN YARD OR TO OTHER OUTLETS.
- 9. LEAKING PIPES OR FITTINGS IN HOUSE OR IN LINE BETWEEN THE METER AND THE HOUSE
- 10. SWIMMING POOL, FISH POND, FOUNTAIN, **SPRINKLER SYSTEMS, WATERING YARD, ETC**.
- 11. SERVICE LINES TO OUTSIDE BUILDINGS LEAKING.
- 12. ANY EQUIPMENT CONNECTED TO WATER LINES.

WATER WASTE IN GALLONS IN 24 HOURS AT 40 POUNDS PRESSURE.	
HOLE	GALS.
•	570
•	970
•	3.600